



BIWIN TECHNOLOGIES CO., LTD.

No. 5, Alley 9, Lane 33-1, Renhe St., Taiping Dist.,
Taichung City 41172, Taiwan

TEL:+886-4-22700988 FAX:+886-4-22700198

<http://www.biwin.com> <http://www.sab-switch.com>

PRODUCT CHANGE NOTICE

To: All Customers (OBM, ODM and OEM), Distributors and Sales Representatives

Date: 26 July, 2016

Subject: Material and Color Change on Actuators and Rotors

Effective Date: 1 November, 2016

Reason for Change:

為使產品的顏色更為一致，因此特將某些產品系列（如以下表格所列）thru-hole type（插件型、通孔型）之推鈕與轉子的材料改為與 SMD type（表面黏著型）相同，意即將兩者的材料統一，且顏色調整為白色。

To make the colors of our products more consistent, the material used on Actuator and Rotor of the thru-hole type in certain product series (listed in the table below) will be changed to that of the SMD type, and the color of the Actuator and Rotor of both types will be white.

Description of the Change:




原本 thru-hole type 之推鈕與轉子的材料與 SMD type 的不同。此 PCN 生效後，某些產品系列（如以下表格所列）的 thru-hole type（插件型、通孔型）之推鈕與轉子的材料將會改為與 SMD type 一樣，且顏色調整為白色。

Originally, the material of the Actuator/ Rotor of the thru-hole type is different from that of the SMD type. After the effectiveness of this PCN, the Actuator/ Rotor material of the thru-hole type of the product series indicated in the chart below will be changed to the thermoplastic we have been using on SMD type, and the color of the Actuator/ Rotor will be white.

Affected products:

1	DI series	5	NP series
2	DT series	6	R9 series
3	SO series	7	RS8 series
4	DP series		

Color comparison:



- If you need the comparison of any specific product, please contact our Sales team.

Best Regards,

General Manager