

Product Termination Notification



Product Group: Tantalum Capacitor Division/Aug 16, 2016/PCN-TC-002-2016

Discontinuation of CLR65 14μF-125V case T2 and 18μF -125V case T3 Capacitors

DESCRIPTION OF CHANGE: Vishay will discontinue two military style CLR65 ratings 14μF-125V case

T2 and $18\mu F$ -125V case T3.

CLASSIFICATION OF CHANGE: Product Discontinuation

REASON FOR CHANGE: We continue to have ongoing performance and yield issue for two CLR65 ratings $14\mu\text{F}$ -125V case T2 and $18\mu\text{F}$ -125V case T3. Vishay has attempted multiple improvement plans without positive results over the past year. Vishay had decided to discontinue any further engineering redesign efforts on these ratings in the silver case. The M39006/09 or CLR65 style has been labeled as inactive for new design since 1982. Vishay will continue to offer the same ratings in the improved and recommended style CLR79 (MIL-PRF-39006/22) tantalum case design. For more details, refer to table 2.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

PRODUCT CATEGORY: Wet Tantalum Capacitors, Military Established Reliability, MIL-PRF-39006/9,

Style CLR65

PART NUMBERS/SERIES/FAMILIES AFFECTED: Table 1

Rated voltage (+85℃) volts, dc	Сар. µF	Cap. tolerance percent	Case size	PIN M39006/09-	
				Failure rate level (%/1	,000 hour)
				L (2)	M (1)
125	14	±20	T2	8198	8403
125	14	±10	T2	8199	8404
125	14	±5	T2	8200	8405
125	18	±20	T3	8201	8406
125	18	±10	T3	8202	8407
125	18	±5	T3	8203	8408

VISHAY BRAND(s): Vishay Israel, Ltd.

TIME SCHEDULE:

Last Time Buy Date: N/A Last Time Shipment Date: N/A

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PTN is considered approved, without further notification.



ISSUED BY: Sahar Eitan, Director Process engineering, Tantalum Capacitors (Eitan.Sahar@vishay.com)

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas	Europe	Asia
Vishay Intertechnology Inc.,	Vishay Israel Ltd.,	Vishay Intertechnology Asia Pte. Ltd.
15 Daigle Lane, Suite 103	New Industrial Park, P.O.B 87	37A Tampines Street 92, #07-00
Sanford, ME 04073	Dimona 8610002	Singapore 528886
USA	Israel	Att: Boon Hooi Tan
Att: Jack Culloton	Att: Albert Mallet	Phone: + 65-6780-7759
Phone: +1-207-490-7208	Phone: +972-8-656-1112	Fax: + 65-6780-7749
Fax: +1-207-490-7213	Fax: +972-8-655-8360	Email: Boonhooi.Tan@Vishay.com
Email: Jack.Culloton@Vishav.com	Email: Albert.Mallet@Vishav.com	•

Table 2: PART NUMBERS AFFECTED

DISCON	ACTIVE	
CLR	CLR79	
FRL L	FRL M	FRL M
M39006/09-8198	M39006/09-8403	M39006/22-0210
M39006/09-8199	M39006/09-8404	M39006/22-0211
M39006/09-8200	M39006/09-8405	M39006/22-0212
M39006/09-8201	M39006/09-8406	M39006/22-0213
M39006/09-8202	M39006/09-8407	M39006/22-0214
M39006/09-8203	M39006/09-8408	M39006/22-0215