



Product Change Notification



Product Group: Vishay Dale/August 25, 2016/PCN-DI-271-2016 Rev 0

IHHP-1212ZH-01 and IHHP-1212AZ-01 Series Product Obsolescence

DESCRIPTION OF CHANGE: The Vishay IHHP-1212 series is becoming obsolete. There will be no replacement for this series. Last time buy timeframe is provided.

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: The IHHP-1212ZH-01 and IHHP-1212AZ-01 are no longer available for Vishay to offer.

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: N/A

PRODUCT CATEGORY: Inductors

PART NUMBERS/SERIES/FAMILIES AFFECTED:

IHHP1212ZHERR33N01 IHHP1212ZHERR47N01 IHHP1212ZHER1R0M01 IHHP1212ZHER4R7M01
IHHP1212AZERR47N01 IHHP1212AZER1R0M01 IHHP1212AZER2R2M01 IHHP1212AZER4R7M01
IHHP1212AZER6R8M01 IHHP1212AZER100M01

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: N/A

Last Time Buy Date: 11/30/2016

Last Time Shipment Date: 5/30/2017

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc
1505 East Highway 50
P. O. Box 180
Yankton, South Dakota 57078
Ph: 1 605-665-9301
Fax: 1 605-665-1627
doug.lillie@vishay.com

Europe

Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
95100 Selb
Germany
Ph: 49-9287-71-2282
Fax: 49-9287-71-2496
jens.walther@vishay.com

Asia

Vishay Asia Pte Ltd.
25 Tampines Street 92
Keppel Building #02-00
Singapore 528877
Ph: +65-788-6668
Fax: +65-788-3383
victor.goh@vishay.com

Vishay Intertechnology, Inc.

Corporate Headquarters 63 Lincoln Highway, Malvern, PA 19355-2143 U.S.A. Phone (610) 644-1300 Fax (610) 296-0657 www.vishay.com

ONE OF THE WORLD'S LARGEST MANUFACTURERS OF DISCRETE SEMICONDUCTORS AND PASSIVE COMPONENTS

Procedure #